


EXHIBIT "G"

NONE

CNA PROPERTY LOSS NOTICE				DATE 08/14/01	
PRODUCER GENATT ASSOCIATES INC. 516-869-8788 FAX		MISCELLANEOUS INFO (Site & Location code) YORK COMMERCIAL CLAIMS		DATE OF LOSS AND TIME 07/26/2001 12:00:00	
3333 NEW HYDE PARK ROAD NEW HYDE PARK NY 11042 5168698765		POLICY TYPE COMPANY AND POLICY NUMBER CO: CNC-CNA COMMERCIAL LINES POL: BM1098742493 (T)		HAIC CODE BM	
CODE: 730021793 SUB CODE:		FLOOD		POLICY DATES EFF: 06/08/2001 EXP: 06/08/2002	
AGENCY CUSTOMER ID		WIND		EFF:	
				EXP:	
INSURED			CONTACT		
NAME AND ADDRESS OF INSURED MAFCOTE INDUSTRIES 108 MAIN STREET NORWALK CT 06851			NAME AND ADDRESS OF INSURED BOB KAMINSKY 413 OXFORD ROAD FRANKLIN OH 45005		
RESIDENCE PHONE (A/C, No) FAX 203-849-9177			BUSINESS PHONE (A/C, No, Ext) (203)847-8500		
NAME AND ADDRESS OF SPOUSE (IF APPLICABLE)			RESIDENCE PHONE (A/C, No) (999)999-9999		
			BUSINESS PHONE (A/C, No, Ext) (513)746-6451		
			WHERE TO CONTACT WORK		
			WHEN TO CONTACT		
LOSS					
LOCATION OF LOSS 413 OXFORD ROAD FRANKLIN OH 45005				POLICE OR FIRE DEPT TO WHICH REPORTED	
KIND OF LOSS FIRE <input type="checkbox"/> LIGHTNING <input type="checkbox"/> FLOOD <input checked="" type="checkbox"/> OTHER (explain) MACHINERY LOSS				PROBABLE AMOUNT ENTIRE LOSS 0.00	
DESCRIPTION OF LOSS & DAMAGE (Use separate sheet, if necessary) INSURED HAS DAMAGE TO BOILER. DUE TO DAMAGED BOILER, INSURED HAS BUSINESS INTERRUPTION.					
POLICY INFORMATION					
MORTGAGEE LIENHOLDER(S) NOT AVAILABLE					
NO MORTGAGEE					
HOMEOWNER POLICIES SECTION 1 ONLY (Complete for coverages A, B, C, D & additional coverages. For Homeowners Section 2 Liability Losses, use ACORD 1)					
A. DWELLING		B. OTHER STRUCTURES		C. PERSONAL PROPERTY	
COVERAGE A. EXCLUDES WIND					
SUBJECT TO FORMS (Insert form numbers as in edition dates, special deductibles)					
FIRE, ALLIED LINES & MULTI-PERIL POLICIES (Complete only those items involved in loss)					
ITEM	SUBJECT OF INSURANCE	AMOUNT	% COINS	DEDUCTIBLE	COVERAGE AND/OR DESCRIPTION OF PROPERTY INSURED
	BLDG <input type="checkbox"/> CNTS				7A114546 XR
	BLDG <input type="checkbox"/> CNTS				BM-50,000,000
	BLDG <input type="checkbox"/> CNTS				ded
SUBJECT TO FORMS (Insert form numbers as in edition dates, special deductibles)					
See Form-Multi Ded					
1.000 POLICY	BUILDING: DEDUCTIBLE: ZONE: PRE FIRM DIFF IN ELEV FORM TYPE GENERAL DWELLING CONDO				
2.000 POLICY	CONTENTS: DEDUCTIBLE: ZONE: FORM TYPE GENERAL DWELLING CONDO				
MARKS/OTHER INSURANCE (List companies, policy numbers, coverages & policy amounts) ONLY: PREVIOUS ADDRESS OF INSURED & WIFE'S MARRIED NAME					
SENT HAS ESTIMATES AND CORRESPONDENCE FOR ADJUSTER					
PH 12:24 AUG 14 01 YORK					
CAT #	PROD #	ADJUSTER ASSIGNED	ADJUSTER #	DATE ASSIGNED	
REPORTED BY CARNE PITIDES-AGENT	REPORTED TO CNC/FNS CALL# 572684-1201	SIGNATURE OF INSURED BY TELEPHONE	SIGNATURE OF PRODUCER		



C 0275



VIA FACSIMILE (516) 869-8765

August 14, 2001

Ed Digioia
Genatt Associates, Inc.
3333 New Hyde Park Road
New Hyde Park, NY 11042

Dear Ed:

Enclosed please find the report on the boiler problem. Despite the memo, the boiler may not be repairable and we are suffering business interruptions. We could default on about \$1 million in sales unless we re-establish the steam from a boiler. A new boiler including installation may exceed \$25,000 in cost. We would like an inspection to determine the cause of the boiler's failure ASAP.

Sincerely,

A handwritten signature in black ink, appearing to read "Steven A. Schulman", written over a horizontal line.

Steven A. Schulman
President

SAS:lss
Enclosure

AUG 13 '01 18:03 FROM MIAMI VALLEY PAPER TO ORATE# PAGE.001

Miami Wabash Paper Company, Inc.
413 Oxford Road
Franklin, Ohio 45005
Phone: 937-746-6451
Fax: 937-746-2139

FAX TRANSMITTAL

NUMBER OF PAGES INCLUDING THIS SHEET: _____ DATE: 8-13-01

TO: SAS

FAX NO: HA

FROM: BK

☒ Urgent ☒ For Your Review ☐ Reply ASAP ☐ Please Comment

REMARKS:

Steve,

- ① The Boiler ruptured on 7/26/01
- ② The reason is either mud or scale buildup
- ③ Mud & scale was removed 1.8 months ago for the first time when I had boiler serviced. It had not been service since installation. Service by Combustion Equipment.
- ④ Repair inspection will be in 8-14-01. Repair cost projected to be \$5,000.00
note to replace old boiler

401-1290

801 S. FERRY ST., DAYTON, OHIO 45402
WHOLESALE DISTRIBUTORS

REFNO:
25 JUN 70
MATERIAL ONLY

1/13/95

SHINE

HC

2. 51.2 034 HR
Lot 12.5 to 54.0
Railroad, etc. 4/10 746 6452

WITH PRICE ONLY	MATERIAL TOTAL	154300
air Lifter of	✓ FREIGHT	—
E WITH R, 1965	TAX	10032
	TOTAL	164332

28 COMPROMISES WITH
EXECUTIVE ORDER 11653

BILLING COPY

WE APPRECIATE YOUR ORDER

AUG 13 '01 18:04
HUG-13-0001 2-JOHNFRL MIAMI VALLEY PAPER
PICKREL BROS. INC.

TO

PORATED

PAGE.004



LATIMER BOILER MFG. CO.

1411 8TH STREET SW
P.O. Box 1527
Cedar Rapids, IA 52406
319-368-0778

SOLD TO:

Pickrel Bros. Inc.
901 South Perry
Dayton, OH 45402
513/461-5960

SHIP TO NOTIFY OFFICE BEFORE SHIPPING

Miami Valley Paper Co.
413 Oxford Road
Franklin, OH 45005

MARK: P.O. #V252327

PROMISED DATE

Date 3/3/95

ACCOUNT NO.	DATE RECEIVED: 2/2/95	DATE SHIPPED:
TERMS: net 30 days	INV. NO.:	SALESPERSON: fax
SHIP VIA best way	<input type="checkbox"/> PPD <input checked="" type="checkbox"/> COL <input type="checkbox"/> COD	FOR SHIPPING POINT: Cedar Rapids, IA

QTY.	PART NO.	DESCRIPTION	UNIT PRICE	TOTAL LIST EXTENSION	DISCOUNT %	TOTAL NET AMOUNT
1		35 H.P. gas-fired POWERPIPS with "G" equipment Standard controls RK7890 flame safeguard w/ runner pilot Safety shut-off valve on thermocouple pilot 2nd safety shut-off solenoid gas valve Motorized gas valves to have fixed orifice in bypass line, drill <u>1</u> Motorized valve to stack end to have end switch to energize valve opposite. stack end Harnish lever handle gas cock on gas inlet Maxitrol 3/8" Model 325-3 gas pressure regulator on pilot gas line U/L label CSB-1 BAC: 1850 S.G.: .61 Drill size: 9/32 S.V.: (2) 1" - 156#				

RECEIVED
AUG 07 1995
PICKREL BROS. INC.
DAYTON, OHIO

SPECIAL INSTRUCTIONS:

CALL DAY 513/461-5960 24 HOURS BEFORE SHIPPING

SUB-TOTAL

TAX (if applicable)

SHIPPING or HANDLING

MISC. CHARGES

BALANCE DUE